# A2X EXPLOSION PROOF PRESSURE TRANSMITTER DRAWING INDEX

| DRAWING NAME | DRAWING NO. | MODEL BREAKDOWN | |
|---|---|---|---|
| | | Process Connection | Electrical Connection |
| A2X M02 C1 | 70A3817 | 1/4 NPT (male) | 1/2 NPT (male) Conduit with Shielded Cable, 3ft |
| A2X M04 C1 | 70A3818 | 1/2 NPT (male) | 1/2 NPT (male) Conduit with Shielded Cable, 3ft |
| A2X F02 C1 | 70A3819 | 1/4 NPT (female) | 1/2 NPT (male) Conduit with Shielded Cable, 3ft |
| A2X M02 C2 | 70A3820 | 1/4 NPT (male) | 1/2 NPT (male) Conduit with Flying Leads, 3ft |
| A2X M04 C2 | 70A3821 | 1/2 NPT (male) | 1/2 NPT (male) Conduit with Flying Leads, 3ft |
| A2X F02 C2 | 70A3822 | 1/4 NPT (female) | 1/2 NPT (male) Conduit with Flying Leads, 3ft |