

# A2X EXPLOSION PROOF PRESSURE TRANSMITTER DRAWING INDEX

DRAWING NAME	DRAWING NO.	MODEL BREAKDOWN	
		Process Connection	Electrical Connection
A2X M02 C1	70A3817	1/4 NPT (male)	1/2 NPT (male) Conduit with Shielded Cable, 3ft
A2X M04 C1	70A3818	1/2 NPT (male)	1/2 NPT (male) Conduit with Shielded Cable, 3ft
A2X F02 C1	70A3819	1/4 NPT (female)	1/2 NPT (male) Conduit with Shielded Cable, 3ft
A2X M02 C2	70A3820	1/4 NPT (male)	1/2 NPT (male) Conduit with Flying Leads, 3ft
A2X M04 C2	70A3821	1/2 NPT (male)	1/2 NPT (male) Conduit with Flying Leads, 3ft
A2X F02 C2	70A3822	1/4 NPT (female)	1/2 NPT (male) Conduit with Flying Leads, 3ft